POPPLETON HISTORIC STUDY

Block

Lot

Address

154

20-37

304-338 N. Carrollton Avenue


Approximate age

1800-1845

1845-1860

1865-1880

1880-1896



Rating Architectural		Condition			
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
\odot	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

The southern portion of this terrace is somewhat younger than the upper, though not by much. Two distinct styles; two builders, likely. South portion Roman glazed brick, stone lintels and sills, steps. Heavy cornice treatment and transomed front windows. There are similar houses in Hampden and east Baltimore. The houses are well cared for.

The north portion has textured brick work in eccentric and varied patterns. Numbers 320-322 and 332-334 have been formstoned. All have marble steps and sills.

Environmental context:

A quiet street, good and well kept houses on both sides. Carrollton is slated to get a foot-bridge across the expressway depression rather than a vehicular bridge. This should assure the quiet character of the street. Street trees are good but a few replacements are needed.



B-2416 304-338 N. Carrolton Street Block 0154 Lots 020-037 Baltimore City Baltimore West Quad.

